

B.S.A. CYCLES LIMITED.

Service Sheet No. 34.

1935 CARBURETTOR SETTINGS.

"Service," January 1935.

No.	Model.	Type.	No.	Float Chamber.	Jct.	Valve.	Needle.
X35-0	1.49 h.p. O.H.V.	93/001	Bore $\frac{3}{8}$ "	see type	45 (20 Pilot)	3	-
B35-1	2.49 h.p. S.V.	74/012	21A	62/099	70	4/4	2
B35-2	2.49 h.p. O.H.V.	74/012	21A	62/079	75	4/4	2
B35-3	2.49 h.p. O.H.V. de Luxe	75/002	28A	64/079	110	5/4	1
R35-4	3.48 h.p. O.H.V. de Luxe	76/001	39A	64/079	140	6/4	2
R35-5	3.48 h.p. O.H.V. Blue Star	76/004	39A	64/079	150	6/4	2
W35-6	4.99 h.p. S.V.	76/112	45A	64/079	140	6/4	1
W35-7	4.99 h.p. O.H.V.	76/024	51A	64/079	170	6/4	2
W35-8	4.99 h.p. O.H.V. Blue Star	89/014P	58A	64/079P	200	29/4	2
W35-9	4.99 h.p. O.H.V. Special	10TT32	Bore $1\frac{1}{8}$ "	14/064	59	4	4
J35-12	4.98 h.p. O.H.V. Twin	4/130	25A	64/078	80	4/4	2
M35-10	5.95 h.p. S.V.	76/130	51A	64/079	180	6/4	3
M35-11	5.95 h.p. O.H.V.	89/011	58A	64/079	220	29/4	2
G35-14	9.86 h.p. S.V. Twin	76/001	39A	64/078	180	6/5	3