

# B.S.A. CYCLES LTD.

---

SERVICE SHEET No. 61.

*November, 1936.*

M21 ~~1937~~ 1937 MOTOR CYCLE AND  
NO. 6B SIDECAR CHASSIS.

The fitting of a No. 6B Sidecar Chassis to a 1937 600 c.c. S.V. machine necessitates the fitting of Rear Brake Lever, Component No. 15-7963, in place of the standard fitting, Component No. 15-7962, to provide clearance for the rear brake operating rod.