

B.S.A. CYCLES LTD.


Service Sheet No. 70A.

March 1937.

PUSH ROD COVER and PUSH ROD COVER JOINT WASHERS for 1937 O.H.V. "B" Models.


1. For Engine Nos.:

HB21-101 to HB21-519
HB22-101 to HB22-243




2. For Engine Nos.:

HB21-520 to HB21-1411
HB22-244 to HB22-1100
HB24-101 to HB24-1184
HB25-101 to HB25-212
HB26-101 to HB26-831



3. For Engine Nos.:

HB21-1412 to HB21-1839
HB22-1101 to HB22-1425
HB24-1185 to HB24-1688
HB25-213 to HB25-244
HB26-832 to HB26-1110



4. For Engine Nos.:

HB21-1840 }
HB22-1426 } Onwards
HB24-1689 }
HB25-244 }
HB26-1110 }

