

B.S.A. CYCLES LTD.

October, 1937.

Service Sheet No. 78.

MOTOR CYCLE.

1938 CARBURETTER SETTINGS.

No.	Model.	Type.	No.	Float Chamber.	Jet.	Jet with Air Cleaner.	Valve.	Needle Position.
						80	4/5	3
B20	250 S.V. Tourer	74/165S	25A	62/079	80	80	4/5	3
B21	250 O.H.V. Sports	74/165	25A	64/079	80	80	4/4	2
B22	250 O.H.V. Empire Star	75/145	33A	64/079	120	110	5/4	3
B23	350 S.V. Tourer	75/145	33A	62/079	110	110	5/4	3
B24	350 O.H.V. Empire Star	76/187	45A	64/077	160	140	6/4	3
B25	350 O.H.V. Competition	76/187	45A	64/077	160	—	6/4	3
B26	350 O.H.V. Sports	76/187	45A	64/077	160	140	6/4	3
M19	350 O.H.V. de Luxe	76/014	45A	64/078	150	150	6/4	2
M20	500 S.V. Tourer	76/014	45A	64/078	170	170	6/4	3
M21	600 S.V. Tourer	76/024	51A	64/078	170	170	6/4	2
M22	500 O.H.V. Sports	76/024	51A	64/078	150	150	6/4	3
M23	500 O.H.V. Empire Star	89/014	58A	64/078	200	180	29/4	2
M24	500 O.H.V. Gold Star...	10TT36	1 1/2 Bore	14/064	370	—	5	4
Y13	750 O.H.V. Vee Twin	76/001	39A	64/078	140	120	6/3	3
G14	1000 S.V. Vee Twin	76/001	39A	64/078	160	150	6/3	1